


SW Corner frl NE 1/4 NW 1/4
Sec 2 - 75-20



This corner had been previously set and
marked with an iron pipe. Waterway
shaping had destroyed it. Set a 1/2" iron pin
w/cap # 5594 10" deep from information
from previous surveys. Abie Davis
5/2/2000