


NW Corner SE⁴
Sec 26-75-20



Set iron pin at junction of new fences replacing
ancient fence. Pin was set to be line with SE⁴ Corner
of Section and point on the west line of the SE⁴
according to iron pin found in corner of road 5834 ft
E. of corner.
4/30/97 Able Davis