

Original Corner For S.E. Cor 36-78-18
 Destroyed by Culvert Construction

Re-established by Bart Shivers,
 Project Engineer of Jasper County,
 on line with E 1/4 Cor & N.E. Cor of S 26
 36-78-18, as surveys Record Book
 shows it was established by Byers

C.M. to N.E. Cor 1-77-18 Not Set
 Found L Iron Used for C.M.

